

Sommario

RosettaCNC plugin Modbus	3
Information	3
Introduction	3
What you can do with modbus interface ?	3
Monitor CNC state	3
Activate Alarms/Warnings	4
Exchange data with Gcode	4
I/O expansion	4
Function control	4
Registers Table	4
Notes	5
Limitation	5

RosettaCNC plugin Modbus



Information

			
Document:	MDUROSETTACNCMODBUS		
Description:	RosettaCNC Modbus interface		
Link:	http://wiki.rosettacnc.com/en/software/rosettacncmodbus		
Release document	Descrizione	Note	Data
01	First release	/	22/10/2020
02	Align with 1.9.2 release	/	28/04/2021
03	Fix IR_GCODE_CMD address and add IR_EXECUTION_INFO info	/	05/10/2021

Introduction

The RosettaCNC board has a MODBUS® SLAVE server inside to exchange information with a PLC. This function is interesting for implementing machine logic inside the PLC.

The implemented protocol is MODBUS® SLAVE TCP. Port, slave id and refresh time can be set in Board settings panel.

The server share the same IP address used by the card for connection to the software on the PC.

The interface contract between the MODBUS® SLAVE in the CNC board and the product that will implement the MODBUS® MASTER connection is bound to the parameter IR_MODBUS_INTERFACE_LEVEL. The first operation to do as soon as communication with the SLAVE is accessed is to retrieve the contents of this register and adapt the subsequent requests to the relative data table model.

The MODBUS_INTERFACE_LEVEL version 1 is currently available.

In the installation package there is the “extra \ modbusview” folder with a .NET example compiled with Visual Studio 2017 Community version with which it is possible to see how easy it is to access the data of the RosettaCNC card by creating a MODBUS® Master.

What you can do with modbus interface ?

Monitor CNC state

Reading INPUT registers you can monitor the CNC state: positions, state, alarms, gcode line during execution, etc

Activate Alarms/Warnings

Writing on HR_CUSTOM_ALARM_xx or HR_CUSTOM_WARNING_xx you can active an alarm/warning. There are max 8 alarms and 8 warnings. Alarm text can be set in CNC control software and is multi language.

Exchange data with Gcode

Bi directinal shared memory is provided. Gcode can write values that can be so visible to the modbus (see G100 P1000 and IR_SHARED_MEMORY registers). Modbus can write values that can be visible to the Gcode (see M167 P1000 and HR_SHARED_MEMORY registers).

Take care that shared memory is retentive so PLC have to context values with CNC states and other informations.

I/O expansion

Use virtual inputs / outputs concept to expando CNC I/O. In this case PLC have only to copi modbus data to real electrical resource.

Function control

Use virtual inputs outputs concept to operate with normal I/O feature. For example if you want PLC to start a Gcode execution, map the Start input function on first virtual input. When PLC active the relative virtual bit CNC starts execution.

If you want to inform PLC about AUX2 output state, map AUX2 to a virtual outputs.

Registers Table

; modbus input registers table		
IR_MODBUS_INTERFACE_LEVEL	30001	; input register [W]: modbus interface level
IR_FIRMWARE_VERSION	30002	; input register [W]: firmware version: ; b15..b08 = version ; b07..b00 = release
IR_SERIAL_NUMBER	30003	; input register [L]: serial number
IR_MACHINE_POSITION_X	30005	; input register [L]: machine position X [mm/1000]
IR_MACHINE_POSITION_Y	30007	; input register [L]: machine position Y [mm/1000]
IR_MACHINE_POSITION_Z	30009	; input register [L]: machine position Z [mm/1000]
IR_TARGET_POSITION_X	30011	; input register [L]: target position X [mm/1000]
IR_TARGET_POSITION_Y	30013	; input register [L]: target position Y [mm/1000]
IR_TARGET_POSITION_Z	30015	; input register [L]: target position Z [mm/1000]
IR_TARGET_POSITION_A	30017	; input register [L]: target position A [°/1000]
IR_TARGET_POSITION_B	30019	; input register [L]: target position B [°/1000]
IR_TARGET_POSITION_C	30021	; input register [L]: target position C [°/1000]
IR_PROGRAM_POSITION_X	30023	; input register [L]: program position X [mm/1000]
IR_PROGRAM_POSITION_Y	30025	; input register [L]: program position Y [mm/1000]
IR_PROGRAM_POSITION_Z	30027	; input register [L]: program position Z [mm/1000]
IR_PROGRAM_POSITION_A	30029	; input register [L]: program position A [°/1000]
IR_PROGRAM_POSITION_B	30031	; input register [L]: program position B [°/1000]
IR_PROGRAM_POSITION_C	30033	; input register [L]: program position C [°/1000]
IR_WORKING_OFFSET_X	30047	; input register [L]: working offset X [mm/1000]
IR_WORKING_OFFSET_Y	30049	; input register [L]: working offset Y [mm/1000]
IR_WORKING_OFFSET_Z	30051	; input register [L]: working offset Z [mm/1000]
IR_WORKING_OFFSET_A	30053	; input register [L]: working offset A [°/1000]
IR_WORKING_OFFSET_B	30055	; input register [L]: working offset B [°/1000]
IR_WORKING_OFFSET_C	30057	; input register [L]: working offset C [°/1000]
IR_ACT_VELOCITY_X	30059	; input register [L]: actual velocity X [mm/min]
IR_ACT_VELOCITY_Y	30061	; input register [L]: actual velocity Y [mm/min]
IR_ACT_VELOCITY_Z	30063	; input register [L]: actual velocity Z [mm/min]
IR_ACT_VELOCITY_A	30065	; input register [L]: actual velocity A [°/min]
IR_ACT_VELOCITY_B	30067	; input register [L]: actual velocity B [°/min]
IR_ACT_VELOCITY_C	30069	; input register [L]: actual velocity C [°/min]
IR_MAIN_CNC_STATE	30071	; input register [W]: main cnc state ; 0: Init ; 1: Init Fieldbus ; 2: Alarm ; 3: Idle ; 4: Homing ; 5: Jog ; 6: Run ; 7: Pause ; 8: Limit ; 9: Measuring tool offset ; 10: Scan 3D ; 11: Safety Idle ; 12: Change Tool ; 13: Safety ; 14: Waiting Main Power ; 15: Retract tool
IR_CNC_STATES	30072	; input register [W]: cnc states ; b00: AllAxesHomed ; b01: ProgramExecutionEndedSuccesfully
IR_ALARM_CODE	30073	; input register [W]: alarm code
IR_ALARM_INFO_FIELD_A	30074	; input register [W]: alarm info field A
IR_ALARM_INFO_FIELD_B	30075	; input register [W]: alarm info field B
IR_GCODE_LINE	30076	; actual gcode line [L]
IR_EXECUTION_INFO	30078	; b00-b07: buffer level [%], b08-b15: program transferred [%]

```

IR_VIRTUAL_OUTPUTS          30079 ; virtual outputs 1 to 16 mask
                                ; b0 = virtual outputs 1
                                ; b1 = virtual outputs 2
                                ;
                                ; b15 = virtual outputs 16

IR_SHARED_MEMORY_01         30080 ; shared memory 32 bit G100 P1000 A parameter
IR_SHARED_MEMORY_02         30082 ; shared memory 32 bit G100 P1000 B parameter
IR_SHARED_MEMORY_03         30084 ; shared memory 32 bit G100 P1000 C parameter
IR_SHARED_MEMORY_04         30086 ; shared memory 32 bit G100 P1000 D parameter
IR_SHARED_MEMORY_05         30088 ; shared memory 32 bit G100 P1000 E parameter
IR_SHARED_MEMORY_06         30090 ; shared memory 32 bit G100 P1000 F parameter
IR_SHARED_MEMORY_07         30092 ; shared memory 32 bit G100 P1000 H parameter
IR_SHARED_MEMORY_08         30094 ; shared memory 32 bit G100 P1000 I parameter

IR_GCODE_CMD                30096 ; actual gcode command [L]

; modbus holding registers table
HR_CUSTOM_ALARM_01          40001 ; set to non zero to sign custom alarm 01
HR_CUSTOM_ALARM_02          40002 ; set to non zero to sign custom alarm 02
HR_CUSTOM_ALARM_03          40003 ; set to non zero to sign custom alarm 03
HR_CUSTOM_ALARM_04          40004 ; set to non zero to sign custom alarm 04
HR_CUSTOM_ALARM_05          40005 ; set to non zero to sign custom alarm 05
HR_CUSTOM_ALARM_06          40006 ; set to non zero to sign custom alarm 06
HR_CUSTOM_ALARM_07          40007 ; set to non zero to sign custom alarm 07
HR_CUSTOM_ALARM_08          40008 ; set to non zero to sign custom alarm 08

HR_CUSTOM_WARNING_01         40009 ; set to non zero to sign custom warning 01
HR_CUSTOM_WARNING_02         40010 ; set to non zero to sign custom warning 02
HR_CUSTOM_WARNING_03         40011 ; set to non zero to sign custom warning 03
HR_CUSTOM_WARNING_04         40012 ; set to non zero to sign custom warning 04
HR_CUSTOM_WARNING_05         40013 ; set to non zero to sign custom warning 05
HR_CUSTOM_WARNING_06         40014 ; set to non zero to sign custom warning 06
HR_CUSTOM_WARNING_07         40015 ; set to non zero to sign custom warning 07
HR_CUSTOM_WARNING_08         40016 ; set to non zero to sign custom warning 08

HR_SHARED_MEMORY_01          40018 ; shared memory 32 bit M167 P1000 (#5740)
HR_SHARED_MEMORY_02          40020 ; shared memory 32 bit M167 P1000 (#5741)
HR_SHARED_MEMORY_03          40022 ; shared memory 32 bit M167 P1000 (#5742)
HR_SHARED_MEMORY_04          40024 ; shared memory 32 bit M167 P1000 (#5743)
HR_SHARED_MEMORY_05          40026 ; shared memory 32 bit M167 P1000 (#5744)
HR_SHARED_MEMORY_06          40028 ; shared memory 32 bit M167 P1000 (#5745)
HR_SHARED_MEMORY_07          40030 ; shared memory 32 bit M167 P1000 (#5746)
HR_SHARED_MEMORY_08          40032 ; shared memory 32 bit M167 P1000 (#5747)
HR_VIRTUAL_INPUTS           40034 ; virtual inputs 1 to 16 (mask)
                                ; b0 = virtual inputs 1
                                ; b1 = virtual inputs 2
                                ;
                                ; b15 = virtual inputs 16

```

Notes

1. To guarantee the atomicity of the LONG data (32bit), the CNC set busy status during the internal updating of the registers. If a MODBUS® MASTER tries to access the information as long as the SLAVE is in the busy state, it will obtain the BUSY state and must remain in polling so that the SLAVE is not unlocked.
2. If you want to use holding registers data you have to set “Enable write operations” in Board settings panel.
3. Take care that shared memory is retentive so PLC have to context values with CNC states and other informations.

Limitation

To optimize the internal data retrieval operations, the SLAVE supports the multiple reading of INPUT register and HOLDING register for a maximum of 32 registers at a time.

Automatically generated document from **RosettaCNC Wiki** - <https://wiki.rosettacnc.com/>

The wiki content is constantly updated by the RosettaCNC development team, so the online version may contain more recent information.